



Little Rock-Fox Fire Protection District
 Fire Prevention Bureau
 5 E North Street, Plano, IL 60545
 Tel: 630-552-3311 / Fax: 630-618-3800

Date: 7-16-13

- Inspection
- Re-inspection
- Complaint

Occupant: Aldi Phone: 630-552-7609

Address: 7030 Burroughs Ave

An inspection of your premises has been conducted in accordance to the Fire Prevention Ordinance of the Little Rock-Fox Fire Protection District and the following violations have been determined:

General Precautions

- Combustible waste (IFC 304)
- Open flames (IFC 308)
- Combustibles within 3 ft of battery chargers for forklifts (IFC 309)
- Fire extinguisher not within 20 ft of battery chargers (IFC 309)
- Vehicles stored indoors (IFC 314)
- Storage within 18" of the ceiling in sprinklered building, or 24" in non-sprinklered building (IFC 315)
- Combustibles in exits (IFC 315)
- Storage under canopies without a sprinkler system (IFC 315)

Fire Resistance Construction

- Openings in walls / ceilings (IFC 703)

Fire Protection Systems

- Sprinkler system needs repair (IFC 901.6.1 NFPA 25)
- Sprinkler heads are blocked / painted (IFC 901.6.1 NFPA 25)
- Hood suppression not covering all equipment (IFC 904.11)
- Standpipes inoperable (IFC 904 NFPA 14)
- Fire extinguisher needs service / not present (IFC 906.1 NFPA 10)
- Fire alarm needs repair (IFC 907.20)
- Fire alarm out of service (IFC 907.20)
- Fire suppression, fire alarm, or fire pump not tested within past year (IFC 901.6.1 NFPA 25/72) Date: 2011
- Hood Suppression System not tested within past 6 months (IFC 901.6.1 NFPA 17) Date: _____

Haz Mat

- Hazardous material located in the building
- Storage tanks in the building (IFC 2703.24)
- Missing NFPA 704 signs (IFC 2703.5)
- Flammable combustible liquids present (IFC 3401)
- Propane in buildings (IFC 3803.2)
- Retail propane < 20 feet from windows, doors, fuel pumps, or combustibles (IFC 3809.1)

Egress

- Exit sign(s) not illuminated (IFC 1010)
- Emergency light(s) not functioning (IFC 1010)
- Items blocking exit(s) (IFC 1011)
- Items concealing exit(s) (IFC 1011.4)
- Doors to corridors in R-use groups not self closing or not 20 minute rated. Transoms/grills not covered with fireproof material (IFC 101 31.3.6.3 / 101 31.3.6.5)

Fire Service Feature

- Address not posted (IFC 505)
- Lock Box (IFC 506)
- Storage near sprinkler risers or alarm panels (IFC 510)

Building Features

- Permanent or fixed extension cords (IFC 605.5)
- Storage within 30" of electrical panels (IFC 605.3)
- Open junction boxes or exposed wiring (IFC 605.6)
- Elevator not fully operational (IFC 607)
- HVAC Needs Repair (IFC 603)

PLEASE SUBMIT THE FOLLOWING REPORTS TO THE FIRE PREVENTION BUREAU REGULARLY PER IFC 901:

- FIRE SUPPRESSION
- FIRE ALARM(S)
- FIRE PUMP
- HOOD SUPPRESSION

Fire detection system needs servicing.

Re-inspection Date: _____

Occupant Signature:

LRFFPD Fire Prevention Bureau



Little Rock-Fox Fire Protection District
 Fire Prevention Bureau
 5 E North Street, Plano, IL 60545
 Tel: 630-552-3311 / Fax: 630-618-3800

Date Inspected: 06/08/12
 By Whom: _____

Business Name		Complex Name		Business Phone		Business Fax		
Aldi				630 552 7607				
Type of Business		Occupancy Date		Hours of Operation		Capacity		
		5/08				25-30		
Street Address		Unit #		Address visible?		Mailing Address (if different)		
7030 Burroughs Ave Plano				[] yes [] no				
1st Business Owner Name & Home Address				Cell Phone		Home Phone		
2nd Business Owner Name & Home Address				Cell Phone		Home Phone		
1st Key Holder / Contact Person			Job Title		Cell Phone		Home Phone	
Kevin Killebrew			Store Manager		630 272 0662			
2nd Key Holder / Contact Person			Job Title		Cell Phone		Home Phone	
Detector Type		Dimensions (ft)		Number of Stories		Basement		
<input type="checkbox"/> smoke <input type="checkbox"/> rate of rise <input type="checkbox"/> heat <input type="checkbox"/> combo		60x30		1		<input checked="" type="checkbox"/> no <input type="checkbox"/> yes Egress: _____		
Building Construction				Gas Meter Location		Electric Disconnect		
Building Construction: Non Combustible Type II Roof Construction: Flat Roof								
Sprinkler System		Stand Pipe		Knox Box				
<input checked="" type="checkbox"/> no <input type="checkbox"/> yes riser location: D-SIDE		<input checked="" type="checkbox"/> no <input type="checkbox"/> yes location: _____		<input checked="" type="checkbox"/> no <input checked="" type="checkbox"/> yes location: ASIDE				
Hydrants ON Burroughs AVE		FDC		Water Shuttle Supply				
Closest: 120 FT		[] no [x] yes						
2nd Hydrant: 300 FT		hydrant location: AN EXTERIOR						
On Site Chemicals (detail here or attach):								
N/A								
MSDS forms sent to the Fire Station? [] yes [] no								
Alarm Monitored By: [] none [x] direct connect [] radio								
Panel location: SPRINKLER ROOM				Alarm Repair Service				
Alarm Company Name: Cintas				Alarm Company Name: Cintas Aurora Tristate				
Phone Number: 630 973 0000				Phone Number: (630) 973 0000 630				

ALDI

Hand-drawn floor plan

